Always important to remember at all times, is that the surface must be smooth and clean of dust or grit. Heavy surface wax build up may cause problems later on with the graphic coming loose.

1

Align the graphic positioned as you wish. A piece of masking tape runs along the top edge will hold it straight as shown and the graphic will hang down.

2

Swing the graphic upward on the tape "hinge" and remove the backing paper. Be careful not to let the letters catch or that you pull the graphics off all together.

3

Slowly let the graphic lower evenly to the surface and squeegee downwards starting from the center and moving outwards removing air bubbles and assuring good adhesion with the finished surface.

4

Slowly remove the carrier paper making sure you don't pull any of the graphic back with it. If properly squeegeed this will not be a problem.

5

A soft cloth can be rubbed over the finished graphic to assure good adhesion of the vinyl to the surface. Small air bubbles may still be able to be worked out but if you cleaned the surface good enough to begin with you should end up with a clean flat finish.